

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/16/2020

Submitted Date:

06/17/2020

Document Number:

689501069**FIELD INSPECTION FORM**Loc ID 328514 Inspector Name: Oakman, Kari On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 68710Name of Operator: PETERSON ENERGY OPERATING INCAddress: 497 N DENVER AVENUECity: LOVELAND State: CO Zip: 80537**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
peterson, andy	970-669-7411	andy.peterson@petersonenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
448878	SPILL OR RELEASE	CL	04/23/2018		-	Bypass Line	EI

General Comment:

COGCC Environmental Inspection of Spill ID 463367 and Remediation Project Nos. 10032 and 11178. Photos attached to document site conditions.

Any corrective actions from previous inspections that have not been addressed are still applicable.

Environmental**Spills/Releases:**

Type of Spill: _____

Estimated Spill Volume: _____

Comment: COGCC Environmental Inspection of and Remediation Project Nos. 10032 and 11178. Based on records review, it appears that remediation of impacted groundwater in Remediation Project 10032 was continued under Remediation Project 11178. Closure of Remediation Project 11178 was approved 7/26/2019; Remediation Project 10032 is still open at this location. Groundwater monitoring wells remain in place (photos 4&5). Operator shall abandon the monitoring wells in accordance with DWR regulations.

Corrective Action: Submit a Supplemental Form 27 requesting closure of Remediation Project 10032, referencing Remediation Project No. 11178

Date: 07/16/2020

Reportable: _____

GPS: Lat _____ Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____ Comment: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689501070	Field Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5177752