

Construction and Stormwater Inspection

June 16, 2020

Operator: GREAT WESTERN OPERATING COMPANY LLC- #10110

Location ID: 459907

Inspection Document #: 697501647

Adams County, CO

SWNW Section 21 T1S R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: TOWER LD PAD
Location ID: 459907



Photo 1. Photo taken from the southwestern location, facing North. Photo illustrates Operator is implementing temporary stabilization (i.e., hydromulch) along portions of the well pad cut slope .

Inspection Photos
Location Name: TOWER LD PAD
Location ID: 459907



Photo 2. Photo taken from the southwestern location, facing Northeast. Photo illustrates Operator is in process of installing the sound wall along the southern well pad.

Inspection Photos
Location Name: TOWER LD PAD
Location ID: 459907



Photo 3. Photo taken from the southwestern location, facing East. See comments under Photo 2. Photo also illustrates the ditch and berm BMP that has been installed around the entire perimeter of location.

Inspection Photos
Location Name: TOWER LD PAD
Location ID: 459907



Photo 4. Photo taken from the southern location, facing Northwest. Photo equipment and supplies being staged for the sound wall installation.

Inspection Photos
Location Name: TOWER LD PAD
Location ID: 459907



Photo 5. Photo taken from the southeastern location, facing Southwest. Photo illustrates Operator has temporarily stabilized the cut slope areas of the production facility.

Inspection Photos
Location Name: TOWER LD PAD
Location ID: 459907



Photo 6. Photo taken from the southeastern location, facing Southwest. See comments under Photo 4. Photo also illustrates the ditch and berm BMP that has been installed around the entire perimeter of location.

Inspection Photos
Location Name: TOWER LD PAD
Location ID: 459907



Photo 7. Photo taken from the northern location, facing West. Photo illustrates topsoil has been temporarily stabilized with equipment tracking and straw crimped mulch.

Inspection Photos
Location Name: TOWER LD PAD
Location ID: 459907



Photo 8. Google Earth aerial imagery taken 9/12/2019. COGCC mapped the outer disturbance area (15.49 acres) using a Trimble Juno 3B handheld device (red line).