

Inspection Photos  
Location Name: Rubyanna 13 Pad  
Location ID: 436071



Photo 1: Pumpjack sign



Photo 2: Some equipment removed; fencing remains

Inspection Photos  
Location Name: Rubyanna 13 Pad  
Location ID: 436071



Photo 3: Equipment removed



Photo 4: Pumpjack Sign

Inspection Photos  
Location Name: Rubyanna 13 Pad  
Location ID: 436071



Photo 5: Equipment removed



Photo 6: Pumpjack Sign

Inspection Photos  
Location Name: Rubyanna 13 Pad  
Location ID: 436071



Photo 7: Equipment removed



Photo 8: Pumpjack Sign

Inspection Photos  
Location Name: Rubyanna 13 Pad  
Location ID: 436071



Colorado Oil and Gas Conservation Commission  
40.48187, -104.83321, 1453.1m, 344°  
Jun 17, 2020 13:53:15

**Photo 9: Stained soil**



Colorado Oil and Gas Conservation Commission  
40.48185, -104.83321, 1452.9m, 137°  
Jun 17, 2020 13:53:21

**Photo 10: Equipment removed**

Inspection Photos  
Location Name: Rubyanna 13 Pad  
Location ID: 436071



Photo 11: Pumpjack Sign



Photo 12: Equipment removed

Inspection Photos  
Location Name: Rubyanna 13 Pad  
Location ID: 436071



Photo 13: Pumpjack Sign



Photo 14: Equipment removed

Inspection Photos  
Location Name: Rubyanna 13 Pad  
Location ID: 436071



Photo 15: Pumpjack Sign



Photo 16: Stained soil removed

Inspection Photos  
Location Name: Rubyanna 13 Pad  
Location ID: 436071




Photo 17: Pumpjack Sign



Photo 18: Stained soil removed

Inspection Photos  
Location Name: Rubyanna 13 Pad  
Location ID: 436071



Photo 19: Trash



Photo 20: Label

Inspection Photos  
Location Name: Rubyanna 13 Pad  
Location ID: 436071



Photo 21: Label



Photo 22: Label

Inspection Photos  
Location Name: Rubyanna 13 Pad  
Location ID: 436071




Photo 23: Stained soil



Photo 24: Stained soil

Inspection Photos  
Location Name: Rubyanna 13 Pad  
Location ID: 436071



**Photo 25: Unused equipment**



**Photo 26: Gas meter removed**