

Inspection Photos
Operator: Big Run
Operating
API: 067-06333
Date: 6/16/2020



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the western fill slope from the northwestern corner facing southward. Sparse revegetation observed on well pad fill slopes, stabilization measures are needed.




Photo 3. View of wattle full of sediment, and sediment deposition down slope from the western fill slope.



Photo 4. View of the reference area, comprised of open grass field with grasses such as western wheatgrass, Indian ricegrass, and smooth brome.