

## Inspection Photos

Operator: Great Western Operating Company LLC

Lease: Weco-P Dechant 42-28 #1

Facility ID/API # 05-017-06890



**1. Meter Shed and pipeline risers**



**2. Tank pad**



## Inspection Photos

Operator: Great Western Operating Company LLC

Lease: Weco-P Dechant 42-28 #1

Facility ID/API # 05-017-06890



**3. Valve broke off of tank**



**4. Where tank sat**

## Inspection Photos

Operator: Great Western Operating Company LLC

Lease: Weco-P Dechant 42-28 #1

Facility ID/API # 05-017-06890



Colorado Oil & Gas Conservation Commission  
38.75803, -102.77871, 39°  
06/17/2020 08:37:41 AM

5. Tank in middle of wheat field



Colorado Oil & Gas Conservation Commission  
38.88778, -102.66744, 1302.0m, 63°  
06/17/2020 08:43:24 AM

6. Tank in wheat field 1000' feet from pad.

