

Inspection Photos  
Location Name: HSR Coyle 13-18A  
Location ID: 331207



Photo 1 WH sign



Photo 2 WH, Weeds starting to grow inside Ag fence

**Inspection Photos**  
**Location Name: HSR Coyle 13-18A**  
**Location ID: 331207**



**Photo 3 Weeds growing along access road**



**Photo 4 weeds growing along access road**