

Inspection Photos
Location Name: Vargas 11-13
Location ID: 332269



Photo 1 WH sign



Photo 2 WH



Location ID: 332269



Photo 3 TB sign



Photo 4 TB

Inspection Photos Location Name: Vargas 11-13 Location ID: 332269



Photo 5 Gas Meter run




Photo 6 Card inside of meter house

Inspection Photos Location Name: Vargas 11-13 Location ID: 332269



Photo 7 Gas Meter runs




Photo 8 Card inside of North brown meter house

Inspection Photos Location Name: Vargas 11-13 Location ID: 332269




Photo 9 card inside of South brown meter house

Photo 10 Horizontal Heated Separator

Inspection Photos
Location Name: Vargas 11-13
Location ID: 332269



Photo 11 ECD