

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/15/2020

Submitted Date:

06/15/2020

Document Number:

701000903

FIELD INSPECTION FORM

Loc ID 337791 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10112

Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC

Address: 5057 KELLER SPRINGS RD STE 650

City: ADDISON State: TX Zip: 75001

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Beard, Alyssa		regulatory@foundationenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
288660	WELL	PR	03/01/2018	GW	125-10598	KNODEL 33-17	PR

General Comment:

Routine Inspection

Location

Lease Road:			
Type	Access		
comment:	Gravel road through pasture		
Corrective Action		Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Lease sign by unit		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	Metal panels around unit and wellhead		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Electric panel		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:	Churchill unit		
Corrective Action:		Date:	

Venting:			
Yes/No			
Comment:			

Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	288660	Type:	WELL	API Number:	125-10598	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing. Casing production. Central meter run for (Knodel 32-17, 33-17, 34-17) 700' N @ 39.71112/-102.09019								
Corrective Action:								Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT