




39.6917, -108.31207, 7365.3ft, 347°
06/18/2020 12:47:04 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Location.

Double Willow 8601D A19 API: 05-045-07218
Inspection: 700402019



39.69215, -108.31197, 7366.1ft, 2°
06/18/2020 12:45:31 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 2. Wellhead.

Double Willow 8601D A19 API: 05-045-07218
Inspection: 700402019



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 3. Separator.

Double Willow 8601D A19 API: 05-045-07218
Inspection: 700402019



39.69176, -108.31204, 7354.7ft, 307°
06/18/2020 12:46:34 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 5. Tank.

Double Willow 8601D A19 API: 05-045-07218
Inspection: 700402019