



**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 294582 Type: WELL API Number: 123-25509 Status: SI Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p><b>COGCC Inspection Report Summary</b>                      On Monday 6/22/20 at approximately 840hrs, I, Inspector Adam Burns, Conducted an on-site inspection at Sledge c 9-28 of Noble Energy at Location ID: 309878 in Weld County, Colorado.                      While there, I observed a production well that Appears to be P/A, form 6(s) #402390734 in process. Reclamation in process.                      No violation of the COGCC rules were observed at the time of inspection.                      This is a summary of inspection report.                      Continuing education inspections</p>	burnsa	06/22/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699101969	Inspection Photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5180505">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5180505</a>