

Inspection Photos
Location Name: C Lisco 14-32
Location ID: 320063



Photo #1 Tanks



Photo #2 Separator

Inspection Photos
Location Name: C Lisco 14-32
Location ID: 320063



Photo #3 compressor house




Photo #4 compressor

Inspection Photos
Location Name: C Lisco 14-32
Location ID: 320063



Photo #5 well head shed



Photo #6 well head