

Inspection Photos
Operator: BP America
API: 067-07193
Date: 6/19/2020



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the southern fill slope from the southern corner facing northwestward. Revegetation is progressing, largely with smooth brome and western wheatgrass.



Photo 3. View of the southeastern project area from the southern corner facing northeastward.



Photo 4. View of musk thistles within the western corner of the project area. Approximately 150 individuals observed.



Photo 5. View of more musk thistles within the project area. Infestation appears to be moving off of the project area and needs to be treated in whole.



Photo 6. View of the reference area, comprised of open grass field with smooth brome and western wheatgrass.