

Inspection Photos
Operator: BP America
API: 067-07060
Date: 6/19/2020



Photo 1. View of the project area from the southern corner facing center.



Photo 2. View of the southern fill slope from the southern corner facing northwestward. Revegetation is progressing, largely with smooth brome and western wheatgrass.



Photo 3. View of Canada thistles growing within the southern project area. Approximately 1000 individuals observed.




Photo 4. View of Canada thistles treated on the well pad, but not treated in the interim reclamation area.



Photo 5. View of the reference area, comprised of ponderosa pine woodland with a grassy understory of smooth brome and western wheatgrass, as well as gambel oaks.