

Inspection Photos
Operator: BP America
API: 067-06909
Date: 6/19/2020



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the southern fill slope from the southwestern corner facing eastward. Revegetation is progressing, largely with smooth brome and western wheatgrass.



Photo 3. View of Canada thistles within the eastern project area. Approximately 150 individuals observed.



Photo 4. View of musk thistles within the southwestern corner of the interim reclamation area. Approximately 50 individuals observed.



Photo 5. View of the reference area, comprised of ponderosa pine forest with a gambel oak, Sandberg bluegrass, and penstemon.