

Inspection Photos

API: 05-009-06630

Operator: CHOLLA PRODUCTION LLC

Inspection Date: 6/22/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-009-06630 | Date: 6/22/2020

Inspection Photos



Photo 1. Facing southwest toward the wellsite. The area of the wellsite does not have crop growth.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06630 | Date: 6/22/2020

Inspection Photos



Photo 2. Facing west at the wellsite. This area is approximately 60 ft. x 60 ft. which does not have adequate crop growth.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06630 | Date: 6/22/2020

Inspection Photos



Photo 3. Facing east at the wellsite. This area is approximately 60 ft. x 60 ft. which does not have adequate crop growth.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06630 | Date: 6/22/2020

Inspection Photos



Photo 4. Facing west toward the surrounding crop field which has uniform crop growth.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06630 | Date: 6/22/2020