

Inspection Photos

API: 05-009-06652

Operator: SOVEREIGN OPERATING COMPANY

Inspection Date: 6/22/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06652 | Date: 6/22/2020

Inspection Photos



Photo 1. Facing south along the former access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06652 | Date: 6/22/2020

Inspection Photos



Photo 2. Facing south at the location. There are areas bare of vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06652 | Date: 6/22/2020

Inspection Photos



Photo 3. Facing south at the location. This area is bare of vegetation which is approximately 80 ft. x 20 ft.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06652 | Date: 6/22/2020

Inspection Photos



Photo 4. Facing north at the location. The vegetation has not adequately re-established.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06652 | Date: 6/22/2020

Inspection Photos



Photo 5. Facing west toward the surrounding undisturbed pasture.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06652 | Date: 6/22/2020