

Inspection Photos
Location Name: Randall 41-10
Location ID: 319664



Photo #1 Tanks.



Photo #2 Leak in Condensate tank

Inspection Photos
Location Name: Randall 41-10
Location ID: 319664



Photo #3 Leak in Condensate tank



Photo #4 Meter



Inspection Photos
Location Name: Randall 41-10
Location ID: 319664



Photo #5 Separator house



Photo #6 Separator house

Inspection Photos
Location Name: Randall 41-10
Location ID: 319664



Photo #7 Separator house



Photo #8 Separator house

Inspection Photos
Location Name: Randall 41-10
Location ID: 319664



Photo #9 Separator house



Photo #10 Well head