

Final Reclamation Inspection

June 16, 2020

Operator: PDC ENERGY INC - 69175

Location ID: 320418

Inspection Document #: 697501664

Adams County, CO

SENE Section 17 T1S R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: MCELWAIN #42-17
Location ID: 320418



Photo 1. Photo taken from the associated offsite tank battery location, facing Northeast. Photo illustrates no crop growth observed.

Inspection Photos
Location Name: MCELWAIN #42-17
Location ID: 320418



Photo 2. Photo taken from the associated offsite tank battery location, facing West. See comments under Photo 1.

Inspection Photos
Location Name: MCELWAIN #42-17
Location ID: 320418



Photo 3. Photo taken from the well location, facing Northwest. Photo illustrates some bare patches with no crop growth.

Inspection Photos
Location Name: MCELWAIN #42-17
Location ID: 320418



Photo 4. Photo taken from the main access road, facing West. Photo illustrates the main access road is still in use by another Operator.