

Final Reclamation Inspection

June 16, 2020

Operator: PDC ENERGY INC - 69175

Location ID: 320229

Inspection Document #: 697501668

Adams County, CO

SENE Section 17 T1S R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: MCELWAIN #3
Location ID: 320229



Photo 1. Photo taken from the well location, facing North. Photo illustrates no crop growth observed which has not been returned to cropland.

Inspection Photos
Location Name: MCELWAIN #3
Location ID: 320229



Photo 2. Photo taken from the well location, facing South. Photo illustrates no crop growth observed throughout the access road which has not been returned to cropland.