

Inspection Photos  
Location Name: Chandler Farms HD 20-212 HN Pad  
Location ID: 441369



Location entrance



Battery signs

**Inspection Photos**  
**Location Name: Chandler Farms HD 20-212 HN Pad**  
**Location ID: 441369**



**Chandler Farms HD 20-389HN wellhead**



**VRT placards**

**Inspection Photos**  
**Location Name: Chandler Farms HD 20-212 HN Pad**  
**Location ID: 441369**



**Crude oil tank placards**



**VRT placards**

**Inspection Photos**  
**Location Name: Chandler Farms HD 20-212 HN Pad**  
**Location ID: 441369**



**VRT placards**



**VRT placards**

**Inspection Photos**  
**Location Name: Chandler Farms HD 20-212 HN Pad**  
**Location ID: 441369**



**Methanol storage wildlife netting**



**Lube oil storage wildlife netting**

**Inspection Photos**  
**Location Name: Chandler Farms HD 20-212 HN Pad**  
**Location ID: 441369**



**Trash**



**Trash**

**Inspection Photos**  
**Location Name: Chandler Farms HD 20-212 HN Pad**  
**Location ID: 441369**



**Trash**



**Trash**

**Inspection Photos**  
**Location Name: Chandler Farms HD 20-212 HN Pad**  
**Location ID: 441369**



**Trash**



**Trash**

**Inspection Photos**  
**Location Name: Chandler Farms HD 20-212 HN Pad**  
**Location ID: 441369**



**Trash**



**Trash**

**Inspection Photos**  
**Location Name: Chandler Farms HD 20-212 HN Pad**  
**Location ID: 441369**



**500 bbl tank berm**