

CAERUS PICEANCE LLC – 10456

API# 05-045-13367 N.PARACHUTE #WF09D M14 596

API# 05-045-13404 N.PARACHUTE #WF10D M14 596

Inspection Date : 6/24/2020



Location overview looking SE



Tank battery

CAERUS PICEANCE LLC – 10456

API# 05-045-13367 N.PARACHUTE #WF09D M14 596

API# 05-045-13404 N.PARACHUTE #WF10D M14 596

Inspection Date : 6/24/2020



Pump housing



Separator

CAERUS PICEANCE LLC – 10456

API# 05-045-13367 N.PARACHUTE #WF09D M14 596

API# 05-045-13404 N.PARACHUTE #WF10D M14 596

Inspection Date : 6/24/2020



API# 05-045-13404 N.PARACHUTE #WF10D M14 596

Injection wellhead missing sign.

Temporarily Abandoned.



API# 05-045-13367 N.PARACHUTE #WF09D M14 596

Injection wellhead with sign.

Temporarily Abandoned.