

Inspection Photos
Operator: BP America
API: 067-07862
Date: 6/24/2020



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the southern fill slope from the southwestern corner facing eastward. Revegetation is progressing with irrigated pasture grasses.



Photo 3. View of the northern project area facing westward.



Photo 4. View of the reference area, comprised of irrigated pasture grasses.