

**Inspection Photos**  
**Operator: BP America**  
**API: 067-07896**  
**Date: 6/24/2020**



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the northern fill slope from the southeastern corner facing westward. Revegetation is progressing, although grazed, with grasses such as crested wheatgrass and shrubby rubber rabbitbrush.



Photo 3. View of the western project area facing southward.



Photo 4. View of the reference area, comprised of pinyon juniper woodland with sagebrush and blue grama understory.