

# State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402431451

Date Received:

06/26/2020

Spill report taken by:

GINTAUTAS, PETER

Spill/Release Point ID:

477085

## SPILL/RELEASE REPORT (INITIAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Refer to COGCC Rule 906.b. for reporting requirements of spills or releases of E&P Waste or produced fluids. Submit a Site Investigation and Remediation Workplan (Form 27) when requested by the Director.

### OPERATOR INFORMATION

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP	Operator No: 47120	<b>Phone Numbers</b>
Address: P O BOX 173779		Phone: (970) 515-1698
City: DENVER	State: CO	Mobile: ( )
Zip: 80217-3779		Email: Gregory_Hamilton@ox y.com
Contact Person: Greg Hamilton		

### INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 402431451

Initial Report Date: 06/25/2020 Date of Discovery: 06/25/2020 Spill Type: Historical Release

#### Spill/Release Point Location:

QTRQTR SENW SEC 28 TWP 3N RNG 66W MERIDIAN 6

Latitude: 40.196133 Longitude: -104.786544

Municipality (if within municipal boundaries): County: WELD

#### Reference Location:

Facility Type: TANK BATTERY

☐ Facility/Location ID No

Spill/Release Point Name: HSR-Jerry D 11-28A

☐ Well API No. (Only if the reference facility is well) 05- -☒ No Existing Facility or Location ID No.

#### Fluid(s) Spilled/Released (please answer Yes/No):

Was one (1) barrel or more spilled outside of berms or secondary containment? Yes

Secondary containment, **including walls & floor regardless of construction material**, must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.

Were Five (5) barrels or more spilled? No

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): Unknown

Estimated Condensate Spill Volume(bbl): Unknown

Estimated Flow Back Fluid Spill Volume(bbl): 0

Estimated Produced Water Spill Volume(bbl): Unknown

Estimated Other E&amp;P Waste Spill Volume(bbl): 0

Estimated Drilling Fluid Spill Volume(bbl): 0

Specify:

#### Land Use:

Current Land Use: OTHER

Other(Specify): Tank Battery Pad

Weather Condition: Sunny, 80°F

Surface Owner: FEE

Other(Specify):

#### Check if impacted or threatened by spill/Release (please answer Yes/No to all that apply):

Waters of the State ☐ Residence/Occupied Structure ☐ Livestock ☐ Public Byway ☐ Surface Water Supply Area ☐

As defined in COGCC 100-Series Rules

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

During plugging and abandonment activities at the HSR-Jerry D 11-28A facility, historical petroleum hydrocarbon impacts were encountered beneath the partially buried produced water vessel. The volume of the release is unknown. The assessment details and analytical results will be summarized in a supplemental report. The topographic Site Location Map showing the geographic setting of the release is provided as Figure 1.

**List Agencies and Other Parties Notified:**

**OTHER NOTIFICATIONS**

<u>Date</u>	<u>Agency/Party</u>	<u>Contact</u>	<u>Phone</u>	<u>Response</u>
6/25/2020	Weld County	Weld County	-	Notified via Office of Emergency Management Online Spill Report
6/25/2020	Landowner	Landowner	-	Notified via Phone

Was there a Grade 1 Gas Leak?      Yes ☐      No ☒

If YES, enter the Document Number of the Grade 1 Gas Leak Report Form 44: \_\_\_\_\_

Was there a reportable accident associated with either a Grade 1 Gas Leak or an E&P waste spill or release?      Yes ☐      No ☒

If YES, enter the Document Number of the Initial Accident Report, Form 22: \_\_\_\_\_

Was there damage during excavation?      Yes ☐      No ☒

If YES, was CO 811 notified prior to excavation?      Yes ☐      No ☐

**OPERATOR COMMENTS:**

A Form 27 Site Investigation and Remediation Workplan (Initial Form) for the removal of the produced water vessel was submitted on November 20, 2019 (Document Number 402238865) and was assigned remediation number 14622.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: Greg Hamilton

Title: Sr. Staff Enviro. Rep. Date: 06/26/2020 Email: Gregory\_Hamilton@oxy.com

**COA Type**

**Description**

	Provide documentation justifying closure request within 45 days of release via supplemental form 19. If investigation and remediation require further actions beyond 45 days then submit an amended form 27 for Project 14622 for approval within 45 days of spill ( by 9August2020).
--	---

**Attachment Check List**

**Att Doc Num**

**Name**

402431451	SPILL/RELEASE REPORT(INITIAL)
402431565	OTHER
402431566	TOPOGRAPHIC MAP
402432763	FORM 19 SUBMITTED

Total Attach: 4 Files

**General Comments**

**User Group**

**Comment**

**Comment Date**

Environmental	off location battery so changed to not at a COGCC location instead of 327402	06/26/2020
---------------	--	------------

Total: 1 comment(s)