

Final Reclamation Inspection

June 22, 2020

Operator: NOBLE ENERGY INC - #100322

Location ID: 309839

Inspection Document #: 697501679

Weld County, CO

NWNE Section 16 T4N R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: RYANN STATE C #16-27
Location ID: 309839




Photo 1. Aerial imagery taken in 2017. Aerial imagery shows two areas circled in red. The Ryann State C 16-27 well was serviced by the northern tank battery circled in red.

Inspection Photos

Location Name: RYANN STATE C #16-27

Location ID: 309839



Photo 2. Photo taken from the southern portion of the northern tank battery, facing North. Photo illustrates the tank battery is in-process of achieving Rule 1003 vegetative compliance.

Inspection Photos
Location Name: RYANN STATE C #16-27
Location ID: 309839



Photo 3. Photo taken from the southeastern portion of the northern tank battery, facing North. Photo illustrates the Operator re-installed the perimeter property fence.

Inspection Photos
Location Name: RYANN STATE C #16-27
Location ID: 309839



Photo 4. Photo taken from the northern entrance for the northern tank battery, facing Northwest. Photo illustrates the Operator removed the culvert.