



40.04608, -108.57606, 6877.9ft, 61°
06/24/2020 03:20:44 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Location.

Calamity Ridge 4401D A23 1N100 05-103-10561
Inspection: 700402134




40.0462, -108.57537, 6887.7ft, 35°
06/24/2020 03:16:55 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 2. Pump jack.

Calamity Ridge 4401D A23 1N100 05-103-10561
Inspection: 700402134




**IN CASE OF EMERGENCY
CONTACT 1-970-361-3007**

CONDENSATE



40.0461, -108.57592, 6877.3ft, 173°

06/24/2020 03:18:11 PM



40.04607, -108.57595, 6877.8ft, 319°
06/24/2020 03:18:37 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 5. Tank liner hole.

Calamity Ridge 4401D A23 1N100 05-103-10561
Inspection: 700402134



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 6. Valve can.

Calamity Ridge 4401D A23 1N100 05-103-10561
Inspection: 700402134

