

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/19/2020

Submitted Date:

06/22/2020

Document Number:

689501073

FIELD INSPECTION FORM

Loc ID 449521 Inspector Name: Oakman, Kari On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10716
 Name of Operator: ROCKY MOUNTAIN MIDSTREAM LLC
 Address: ONE WILLIAMS CENTER
 City: TULSA State: OK Zip: 74172

Findings:

- 2 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Ron Hudson		ron.hudson@williams.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
465115	SPILL OR RELEASE	AC	06/07/2019		-	Ottessen 06-370-HC	EI

General Comment:

[COGCC Environmental Inspection of Spill ID 465115. Wellheads and adjacent battery not inspected.](#)

Inspected Facilities

Facility ID: 465115 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

Environmental

Spills/Releases:

Type of Spill: OIL Estimated Spill Volume: _____

Comment: Spill ID 465115 reported to the COGCC 6/4/2019; Form 19 lists date of discovery as 5/31/2019. Form 19 reports a crude oil spill at the LACT unit. No surface impacts were observed at the spill area at the time of inspection. No Supplemental Form 19 has been submitted for this spill and no cleanup information has been provided by the operator.

Corrective Action: Per Rule 906.b., the Operator shall make a supplemental report on Form 19 not more than 10 calendar days after the spill/release is discovered; the Supplemental report for this spill was due 6/10/2019. Operator shall submit a Form 19 Supplemental Report that documents the successful Remediation of the release. Supporting documentation shall include confirmation soil samples to document removal of impacts from soil in the release area and a site diagram that illustrates the release extent and location of confirmation soil samples.

Date: 06/10/2019

Reportable: _____ GPS: Lat _____ Long _____
 Proximity to Surface Water: _____ Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
402428123	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5180914