



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Location.

WRD Unit 20-31

API: 05-103-09924

Inspection: 700402171



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 2. Well.

WRD Unit 20-31

API: 05-103-09924

Inspection: 700402171



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 3. Separator.

WRD Unit 20-31

API: 05-103-09924

Inspection: 700402171







40.12511, -108.1951, 6023 1ft, 207°
06/26/2020 10:15:08 AM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 6. Weed debris.

WRD Unit 20-31

API: 05-103-09924

Inspection: 700402171