



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Location.

Ant Hill 30-42

API: 05-103-09919

Inspection: 700402176



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 2. Pump jack.

Ant Hill 30-42

API: 05-103-09919

Inspection: 700402176



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 3. Separator.

Ant Hill 30-42

API: 05-103-09919

Inspection: 700402176



40.10779, -108.20996, 5951.9ft, 335°
06/26/2020 11:30:15 AM





COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

**Photo 6. Storm water channel continuing below
location.**

Ant Hill 30-42

API: 05-103-09919

Inspection: 700402176



40.10791, -108.21004, 5960.9ft, 304°
06/26/2020 11:26:04 AM



40.10792, -108.21013, 5963 2ft, 339°
06/26/2020 11:26:15 AM

