

Inspection Photos

Loc#335571

Operator: Terra

Inspection Number: 692402335

Inspection Date: 6/23/20



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location.

June 23, 2020



Photo#2:
Topsoil Stockpile.

June 23, 2020



Photo#3:
Wattles installed as perimeter control.

Photo#4:
Wattles installed as perimeter control

June 23, 2020