

Interim Reclamation Inspection

June 22, 2020

Operator: NOBLE ENERGY INC - #100322

Location ID: 330083

Inspection Document #: 697501674

Weld County, CO

NENE Section 8 T4N R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources



Photo 1. Photo taken from the wellhead, facing South. Photo illustrates the well is currently in shut-in status. There were no reclamation issues observed at this well location.

Inspection Photos
Location Name: RUFF #8-114
Location ID: 330083



Photo 2. Photo taken from the wellhead, facing East. See comments under Photo 1.