

Interim Reclamation Inspection

June 22, 2020

Operator: NOBLE ENERGY INC - #100322

Location ID: 319353

Inspection Document #: 697501683

Weld County, CO

NWNE Section 8 T4N R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: RUFF #1
Location ID: 319353



Photo 1. Photo taken from the wellhead, facing South. Photo illustrates the well appears to currently be in temporarily abandoned status. The associated offsite tank battery is located to the north ~0.1 miles. There were no reclamation issues observed at this well location or the tank battery.

Inspection Photos
Location Name: RUFF #1
Location ID: 319353



Photo 2. Photo taken from the wellhead. See comments under Photo 1.

Inspection Photos
Location Name: RUFF #1
Location ID: 319353



Photo 3. Photo taken from the wellhead. See comments under Photo 1.