


Inspection Photos
Location Name: GV 17-32-696
Location ID: 335107 & Spill/Release ID: 476937
Inspection Date: June 24, 2020



Location sign



Overview of the tank battery

Inspection Photos

Location Name: GV 17-32-696

Location ID: 335107 & Spill/Release ID: 476937

Inspection Date: June 24, 2020



Overview of the tank battery



Tank battery secondary containment liner and residual staining ring



Inspection Photos

Location Name: GV 17-32-696

Location ID: 335107 & Spill/Release ID: 476937

Inspection Date: June 24, 2020



Tank battery secondary containment



Tank battery secondary containment