

Inspection Photos
Location Name: Eilts-Bradley 1-14
Location ID: 316765



Photo 1. Overview of location taken facing east.



Photo 2. Well temporarily abandoned.



Inspection Photos
Location Name: Eilts-Bradley 1-14
Location ID: 316765



Photo 3. Example of stained soil on location.



Photo 4. Example of stained soil on location.