





COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 2. Well.

Continental 6-22

API: 05-103-08540

Inspection: 700402208



39.77487, -108.61213, 6737.4ft, 316°
06/30/2020 10:16:55 AM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 3. Meter building, separator & pit.

Continental 6-22

API: 05-103-08540

Inspection: 700402208



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 4. Well head pit.

Continental 6-22

API: 05-103-08540

Inspection: 700402208



39.7749, -108.61218, 6735.4ft, 326°

06/30/2020 10:16:26 AM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 5. Separator pit.

Continental 6-22

API: 05-103-08540

Inspection: 700402208



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 6. Well sign.

Continental 6-22


API: 05-103-08540

Inspection: 700402208





39.77489, -108.61191, 6736.0ft, 191°
06/30/2020 10:12:43 AM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 9. FLIR image of well head.

Continental 6-22

API: 05-103-08540

Inspection: 700402208