



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Location.

Coors 8-22 API: 05-103-08673
Inspection: 700402212



39.76885, -108.60316, 6901.4ft, 236°
06/30/2020 10:42:35 AM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 2. Well.

Coors 8-22 API: 05-103-08673
Inspection: 700402212





39.76863, -108.6035, 6911.8ft, 263°
06/30/2020 10:43:57 AM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 5. Well head sign.

Coors 8-22 API: 05-103-08673
Inspection: 700402212





39.76881, -108.6032, 6909.0ft, 331°
06/30/2020 10:47:59 AM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 7. Well head gas leak.

Coors 8-22 API: 05-103-08673
Inspection: 700402212

