



39.76278, -108.60903, 7029 7ft, 180°
06/30/2020 10:54:32 AM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 2. Well.

Terra I-27X API: 05-103-08682
Inspection: 700402216



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 3. Pit, separator, meter building.

Terra I-27X API: 05-103-08682
Inspection: 700402216



39.76223, -108.60894, 7050 5ft, 252°
06/30/2020 10:58:18 AM



39.76227, -108.60896, 7051.3ft, 246°
06/30/2020 10:58:02 AM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 6. Unmarker deadman next to well pit.

Terra I-27X API: 05-103-08682
Inspection: 700402216

