

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/24/2020

Submitted Date:

06/24/2020

Document Number:

699301999**FIELD INSPECTION FORM**

Loc ID 331874 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**13 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name | Phone | Email                         | Comment                         |
|--------------|-------|-------------------------------|---------------------------------|
| ,            |       | COGCCinspections@anadarko.com | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name     | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------|-------------|
| 267663      | WELL | TA     | 03/13/2019  | GW         | 123-21430 | CANNON LAND 6-15A | TA          |

**General Comment:**

**Location**Overall Good: ☒

|                      |                      |       |  |
|----------------------|----------------------|-------|--|
| <b>Signs/Marker:</b> |                      |       |  |
| Type                 | WELLHEAD             |       |  |
| Comment:             | adequate             |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | BATTERY              |       |  |
| Comment:             | adequate             |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | TANK LABELS/PLACARDS |       |  |
| Comment:             | adequate             |       |  |
| Corrective Action:   |                      | Date: |  |

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

|                    |              |       |  |
|--------------------|--------------|-------|--|
| <b>Fencing/:</b>   |              |       |  |
| Type               | WELLHEAD     |       |  |
| Comment:           | Ag fence     |       |  |
| Corrective Action: |              | Date: |  |
| Type               | TANK BATTERY |       |  |
| Comment:           | barb wire    |       |  |
| Corrective Action: |              | Date: |  |
| Type               | SEPARATOR    |       |  |
| Comment:           | barb wire    |       |  |
| Corrective Action: |              | Date: |  |

|                                   |                    |       |                 |
|-----------------------------------|--------------------|-------|-----------------|
| <b>Equipment:</b>                 |                    |       | corrective date |
| Type: Horizontal Heated Separator | # 1                |       |                 |
| Comment:                          |                    |       |                 |
| Corrective Action:                |                    | Date: |                 |
| Type: Bradenhead                  | # 1                |       |                 |
| Comment:                          | exposed at surface |       |                 |
| Corrective Action:                |                    | Date: |                 |
| Type: Bird Protectors             | # 1                |       |                 |

|                     |  |       |                  |
|---------------------|--|-------|------------------|
| Comment:            |  |       |                  |
| Corrective Action:  |  | Date: |                  |
| Type: Gas Meter Run | # 1  |       |                  |
| Comment:            | card in White meter house (White) indicates calibration is current                               |       |                  |
| Corrective Action:  |  | Date: |                  |
| Type: Gas Meter Run | # 1  |       |                  |
| Comment:            | Card inside of Brown meter house indicates that Calibration is out of date and needs calibration |       |                  |
| Corrective Action:  | Comply with Rule 328/329 Measurement of oil/gas.   |       | Date: 09/24/2020 |

**Tanks and Berms:**

| Contents           | # | Capacity | Type         | Tank ID | SE GPS |
|--------------------|---|----------|--------------|---------|--------|
| PRODUCED WATER     | 1 | <50 BBLS | PBV CONCRETE |         | ,      |
| Comment:           |   |          |              |         |        |
| Corrective Action: |   |          |              |         | Date:  |

**Paint**

|                  |        |
|------------------|--------|
| Condition        |        |
| Other (Content)  |        |
| Other (Capacity) | 43 bbl |
| Other (Type)     |        |

**Berms**

| Type               | Capacity                          | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|-----------------------------------|---------------------|---------------------|-------------|
| Earth              | Adequate                          | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           | shars containment with crude tank |                     |                     |             |
| Corrective Action: |                                   |                     |                     | Date:       |

| Contents           | # | Capacity | Type      | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| CRUDE OIL          | 1 | 300 BBLS | STEEL AST |         | ,      |
| Comment:           |   |          |           |         |        |
| Corrective Action: |   |          |           |         | Date:  |

**Paint**

|                  |          |
|------------------|----------|
| Condition        | Adequate |
| Other (Content)  |          |
| Other (Capacity) |          |
| Other (Type)     |          |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Earth              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

**Venting:**

|        |    |  |  |
|--------|----|--|--|
| Yes/No | NO |  |  |
|--------|----|--|--|

|                    |  |       |  |
|--------------------|--|-------|--|
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |
| <b>Flaring:</b>    |  |       |  |
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Inspected Facilities**Facility ID: 267663 Type: WELL API Number: 123-21430 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: TA since 3-13-2019, Form 21 (MIT) Doc # 401950473 submitted on 2-6-2019 and is approved, Form 4 (TA) Doc # 402317627 Submitted 2-19-2020 and is approved.Corrective Action:  Date: \_\_\_\_\_**COGCC Comments**

| Comment  | User   | Date       |
|--|--------|------------|
| <p>COGCC Inspection Report Summary</p> <p>On Wednesday 6/24/2020 at approximately 1340 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a Kerr McGee location:</p> <p style="text-align: center;">Cannon Land 6-15 at API # 05-123-21430 in Weld County Colorado.</p> <p>While there, I observed wellsite and tank battery, TA since 3-13-2019, Form 21 (MIT) Doc # 401950473 submitted on 2-6-2019 and is approved, Form 4 (TA) Doc # 402317627 Submitted 2-19-2020 and is approved.</p> <p>During this inspection the following compliance issues were observed:<br/> 328/329 Measurment of oil/gas: Card inside of Brown meter house indicates that Calibration is out of date and needs calibration, CA date 9-24-2020 see photo 4.<br/> See attached photos.<br/> Location is dry, weather is clear.<br/> A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.<br/> Continuing education COGCC Inspection Report Summary.<br/> This is a summary of inspection report.</p> | revasr | 06/24/2020 |

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 402430733    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5183286">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5183286</a> |
| 699302000    | location pics        | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5183280">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5183280</a> |