

Inspection Photos

API#045-09150

Operator: Caerus

Inspection #: 692402341

Inspection Date: 6/25/20



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to Southeast.

June 25, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus PA Buerger API#045-09150



Photo#2:
Gravel remains on Pad area.

June 25, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#3:
Graveled access road remains.

Caerus PA Buerger API#045-09150



Photo#4:
Vegetation on slopes, insert close up of ground conditions.



Photo#5:



June 25, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus PA Buerger API#045-09150



Photo#6:
BMPS installed.



Photo#7:
BMPS installed.

June 25, 2020