

Final Reclamation Inspection

June 22, 2020

Operator: NOBLE ENERGY INC - #100322

Location ID: 309896

Inspection Document #: 697501687

Weld County, CO

NENE Section 16 T4N R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: RYANN STATE C #16-1

Location ID: 309896




Photo 1. Aerial imagery taken in 2017. Aerial imagery shows the southern tank battery (circled in red) that was inspected.

Inspection Photos

Location Name: RYANN STATE C #16-1

Location ID: 309896



Photo 2. Photo taken from the southern tank battery, facing West. Photo illustrates fencing has been re-installed around the perimeter of the tank battery.

Inspection Photos

Location Name: RYANN STATE C #16-1

Location ID: 309896



Photo 3. Photo taken from the southern tank battery, facing South. Photo illustrates Operator has performed final reclamation activities. Weed management will need to be performed soon.

Inspection Photos

Location Name: RYANN STATE C #16-1

Location ID: 309896



Photo 4. Photo taken from the northern tank battery, facing North. Photo illustrates a ground monitoring well that will be removed, as the Remediation Project has been approved. Germination was observed but Operator will likely need to perform additional reclamation activities, as germination of desirable species was not uniform.

Inspection Photos

Location Name: RYANN STATE C #16-1

Location ID: 309896



Photo 5. Photo taken from the southern tank battery, facing North. See comments under Photo 4.

Inspection Photos

Location Name: RYANN STATE C #16-1

Location ID: 309896



Photo 6. Reference photo taken south of the tank battery, facing West.