

Inspection Photos
Location Name: Latham 41-1 Tank Battery
Location ID: 468441



Photo #1 Tank Battery



Photo #2 Separator & ECD's

Inspection Photos
Location Name: Latham 41-1 Tank Battery
Location ID: 468441



Photo #3 Separators



Photo #4 Gas lift skid



Inspection Photos
Location Name: Latham 41-1 Tank Battery
Location ID: 468441



Photo #5 Unused Fence



Photo #6 Trash

Inspection Photos
Location Name: Latham 41-1 Tank Battery
Location ID: 468441



Photo #7 Unused Equipment



Photo #8 Unused equipment



Inspection Photos
Location Name: Latham 41-1 Tank Battery
Location ID: 468441



Photo #9 Unused Equipment



Photo #10 Trash

Inspection Photos
Location Name: Latham 41-1 Tank Battery
Location ID: 468441



Photo #11 Unused Equipment



Photo #12 Unused Equipment

