

Inspection Photos
Location Name: Latham 32-1 Pad
Location ID: 429499



Photo #1 Separators & ECD



Photo #2 Tank Battery



Inspection Photos
Location Name: Latham 32-1 Pad
Location ID: 429499



Photo #3 Wells




Photo #4 Unused Equipment & Trash



Inspection Photos
Location Name: Latham 32-1 Pad
Location ID: 429499



Photo #5 Unused equipment



Photo #6 Unused equipment



Inspection Photos
Location Name: Latham 32-1 Pad
Location ID: 429499



Photo #7 Unused Fence



Photo #8 Hole in liner

