

Inspection Photos
Location Name: Latham 43-1 Pad
Location ID: 429485



Photo #1 Wells



Photo #2 Separators & ECD

Inspection Photos
Location Name: Latham 43-1 Pad
Location ID: 429485



Photo #3 Tank Battery



Photo #4 Unused buckets

Inspection Photos
Location Name: Latham 43-1 Pad
Location ID: 429485



Photo #5 Unused equipment & Stained soil



Photo #6 Stained soil

Inspection Photos
Location Name: Latham 43-1 Pad
Location ID: 429485



Photo #7 Stained soil



Photo #8 Stained soil

Inspection Photos
Location Name: Latham 43-1 Pad
Location ID: 429485



Photo #9 Unused Rags