

Final Reclamation Inspection

June 24, 2020

Operator: BATES* JAMES EDWARD - 6575

API #: 05-005-06064

Inspection Document #: 697501689

Arapahoe County, CO

SWSW Section 14 T4S R60W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources




Photo 1. COGCC GISOnline aerial imagery from 2009 during active operations. Imagery illustrates the location of the well and the offsite tank battery.

Inspection Photos
Location Name: PRICE #1
API #: 05-005-06064



Photo 2. Zoomed in photo of the tank battery location. Photo illustrates the total disturbance including a potential produced water spill from a pit.

Inspection Photos
Location Name: PRICE #1
API #: 05-005-06064




Photo 3. COGCC drone aerial imagery captured on June 24, 2020 illustrates the approximate disturbance area (red polygon) needing to be reclaimed. The southern disturbance area appears to be from a produced water spill from a pit.

Inspection Photos
Location Name: PRICE #1
API #: 05-005-06064



Photo 4. Photo taken from the northern tank battery, facing Southwest. Photo illustrates no reclamation activities have been performed.

Inspection Photos
Location Name: PRICE #1
API #: 05-005-06064



Photo 5. Photo taken from the northern tank battery, facing North. See comments under Photo 4.

Inspection Photos
Location Name: PRICE #1
API #: 05-005-06064



Photo 6. Photo taken from the northern tank battery, facing South. See comments under Photo 4.

Inspection Photos
Location Name: PRICE #1
API #: 05-005-06064



Photo 7. Tank battery reference photo taken 1/8/2020 northwest of the tank battery, facing West. Photo illustrates blue grama as the dominant vegetative cover.