

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/24/2020

Submitted Date:

06/24/2020

Document Number:

701000930**FIELD INSPECTION FORM**

Loc ID 337806 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 10112Name of Operator: FOUNDATION ENERGY MANAGEMENT LLCAddress: 5057 KELLER SPRINGS RD STE 650City: ADDISON State: TX Zip: 75001**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION  
☐ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**8 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Beard, Alyssa		regulatory@foundationenergy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
288759	WELL	PR	07/01/2008	GW	125-10613	KNODEL 41-16	PR

**General Comment:**

Routine Inspection

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Gravel road through pasture		
Corrective Action		Date:	

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Lease sign by unit		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	Metal panels around unit and wellhead		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Pump Jack	# 1		
Comment:	Sentry unit		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Electric panel		
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No			
Comment:			

Corrective Action:		Date:	
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

Inspected Facilities									
Facility ID:	288759	Type:	WELL	API Number:	125-10613	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing. Casing production. Central meter run for (Knodel 41-16, 42-16) 1000' SE @ 39.71350/-102.06448								
Corrective Action:								Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT