

Inspection Photos
Location Name: Open Range 18
Location ID: 447512



Photo 1. Overview of location taken facing northeast.

Inspection Photos
Location Name: Open Range 18
Location ID: 447512



Photo 2. Stained soil.



Photo 3. Stained soil.

