

Inspection Photos
Location Name: Dolph UPRR 62N-66W
Location ID: 336264



Photo 1 WH/sign



Photo 2 WH/sign

Inspection Photos
Location Name: Dolph UPRR 62N-66W
Location ID: 336264



Photo 3 WH/sign



Photo 4 WH/sign

Inspection Photos
Location Name: Dolph UPRR 62N-66W
Location ID: 336264




Photo 5 WH/sign



Photo 6 ECD

Inspection Photos

Location Name: Dolph UPRR 62N-66W
Location ID: 336264



Photo 7 Gas Meter Run




Photo 8 card inside meter house indicates that calibration is due.

Inspection Photos
Location Name: Dolph UPRR 62N-66W
Location ID: 336264

Location ID: 336264



Photo 9 Gas Meter Run




Photo 10 card inside meter house indicates that calibration is current.

Inspection Photos
Location Name: Dolph UPRR 62N-66W
Location ID: 336264



Photo 11 Horizontal Heated Separators



Photo 12 flow lines.

Inspection Photos
Location Name: Dolph UPRR 62N-66W
Location ID: 336264



Photo 13 TB signs



Photo 14 TB