

Inspection Photos

API: 071-08625

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 6/29/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-08625 | Date: 6/29/2020

Inspection Photos



Photo 1. Facing south near the beginning of the access road. The water bar installed is diverting stormwater off the road however, erosion channels have developed.



Photo 2. Facing back to the north. There are erosion channels near the water bar shown in previous photo.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08625 | Date: 6/29/2020

Inspection Photos



Photo 3. Facing northeast along the road ascending the hillside. Rip/rap is installed along the side of the road to prevent erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08625 | Date: 6/29/2020

Inspection Photos



Photo 4. There is erosion occurring down the road and stormwater is not properly diverted toward the culvert in this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08625 | Date: 6/29/2020

Inspection Photos



Photo 5. Facing west along the road near the top of the hill. There is an erosion channel that has formed in this area.



Photo 6. Facing back toward the east near the top of the hill shown in area of previous photo. Stormwater is not fully being divert toward the culvert at this point.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos



Photo 7. Facing west along the access road at the top of the ridge. The road is stabilized along this portion of the road to the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08625 | Date: 6/29/2020

Inspection Photos



Photo 8. Facing northwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08625 | Date: 6/29/2020

Inspection Photos



Photo 9. Facing southwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08625 | Date: 6/29/2020

Inspection Photos



Photo 10. Facing east toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-08625 | Date: 6/29/2020