

Inspection Photos
Location Name: Counts 22-30
Location ID: 313335



Photo 1. Overview of location taken facing south.

Inspection Photos
Location Name: Counts 22-30
Location ID: 313335



Photo 2. Incomplete tank labels. Annual weeds on location.



Photo 3. Tank top insulation peeling off.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources