

Inspection Photos
Location Name: Bighole-Federal 14-2
Location ID: 312921



Photo 1. Overview of location taken facing south.



Inspection Photos
Location Name: Bighole-Federal 14-2
Location ID: 312921



Photo 2. Tank top insulation on 400 BBL tank peeling off.



Photo 3. Separator appears inoperable.